

EXPLODED VIEW OF CORDLESS DRILL RDP-SCDI20

1.	1	1.	Left hand side screw	1
2.	1	2.	Drill chuck	1
3.	1	3.	Torque Setting Ring	1
4.	1	4.	Variable speed ring	1
5.	1	5.	Gear box	1
6.	1	6.	Speed changing plate	1
7.	1	7.	Shrounel	1
8.	1	8.	Plate spring	1
9.	1	9.	Switch lock button	1
10.	2	10.	Inductore	2
11.	1	11.	Magnetic ring	1
12.	1	12.	Switch	1
13.	1	13.	LED	1
14.	1	14.	Tagging screw	1
15.	1	15.	Protective plate	1
16.	1	16.	Battery Clip	1
17.	2	17.	Nut	2
18.	1	18.	Belt hook	1
19.	1	19.	Tagging screw	1
20.	1	20.	Lampshade	1
21.	2	21.	The magnet	2
22.	1	22.	Screwdriver head	1
23.	1	23.	Enclosure bottom cap	1
24.	10	24.	Tagging screw	10

