888 - Exploded View (Page 1 of 5)

1. 10#K rubber cover
2. 6#K keypad
3. 14# screw cover
4. Crosshead plate screw M2.5×8 (2pcs)
5. 3#K top cover
6. 13# connecting staff (2pcs)
7. Housing module
8. Bracket core module
9. Crosshead plate tapping screw ST2.9×8 (5pcs)
10. Base module
11. 9#K base rubber cover



Figure 1

ТАШЕВ-ГАЛВИНГ ООД
www.tashev-galving.com

888 - Exploded View (Page 2 of 5)



Figure 2

ТАШЕВ-ГАЛВИНГ ООД
www.tashev-galving.com

7-1. K window frame module (2pcs)
7-2. 1#K housing
7-3. 603-05-6# screw
7-4. Outlet
7-5. Battery spring pack
7-6. 603-05-15# rubber plug
7-7. 5#K battery cover

888 - Exploded View (Page 3 of 5)

8-1. Crosshead plate screw M2.5×6 (4pcs)
8-2. K 1# circuit board
8-3. 603-02-18# round spacer
8-4. 603-02-16# round spacer
8-5. 603-2# circuit board
8-6. Crosshead plate screw M2×6 (4pcs)
8-7. Nut M2.5
8-8. 603-3# alarm circuit board
8-9. 603-02-15# spacer
8-10. φ4 gasket
8-11. φ3 gasket
8-12.Crosshead plate screw M2.5×10
8-13. Hairspring (4pcs)
8-14. 603-6# circuit board (2pcs)
8-15. 603-4# circuit board
8-16. Pin (8pcs)
8-17. Core module
8-18. Gimbal module
8-19. 2.5 spring gasket (3pcs)
8-20. Crosshead plate screw M2.5×10 (3pcs)
8-21. 603-02-14# tension rod (2pcs)
8-22. 603-02-1# bracket
8-23. 603-5# circuit board (2pcs)
8-24. Crosshead sunk screw M2.5×6 (3pcs)



Figure 3

ТАШЕВ-ГАЛВИНГ ООД
www.tashev-galving.com

888 - Exploded View (Page 4 of 5)



Figure 4

8-17-1. 603-04-4# reflecting head
8-17-2. Crosshead plate screw M2×12
8-17-3. φ4.5×6 cylindrical lens (3pcs)
8-17-4. Laser line source module (3pcs)
8-17-5. Crosshead plate screw M2×8 (4pcs)
8-17-6. 2.5 spring gasket (2pcs)
8-17-7. Crosshead plate screw M2.5×10 (2pcs)
8-17-8. Crosshead plate screw M2×10
8-17-9. 603-04-001-3# adjusting board
8-17-10. 603-04-5# weight block
8-17-11. Crosshead plate screw M2×8 (2pcs)
8-17-12. Crosshead plate screw M2×6 (8pcs)
8-17-13. 603-04-6# weight piece
8-17-14. 603-04-001-1# bracket plate

ТАЩЕВ-ГАЛВИНГ ООД
www.tashev-galving.com

888 - Exploded View (Page 5 of 5)



Figure 5

10-1. 8# loop
10-2. Switch hook
10-3. φ2 gasket (2pcs)
10-4. Nut M2 (2pcs)
10-5. 603-01-4# bottom housing (2pcs)
10-6. Slipper module
10-7. 603-01-10# connection board
10-8. Pendulum module
10-9. Bottom plate module
10-10. Crosshead plate screw M2.5×8 (4pcs)
10-11. 603-01-1# base
10-12. Crosshead plate screw M2×12 (2pcs)

ТАШЕВ-ГАЛВИНГ ООО
www.tashev-galving.com