



17-teilig

1 Handhalter 816 R Kraftform mit Schnellwechselfutter Rapidaptor

	
05059295001	
	816 R 1 x 1/4"x119
	851/4 Z PH 1 x PH 1x89; 1 x PH 2x89; 1 x PH 3x89
	855/4 Z PZ 1 x PZ 1x89; 1 x PZ 2x89; 1 x PZ 3x89
	867/4 Z TORX® B0 1 x TX 10x89; 1 x TX 15x89; 1 x TX 20x89; 1 x TX 25x89; 1 x TX 30x89
	800/4 Z 1 x 1,0x5,5x89
	840/4 Z Hex-Plus 1 x 3,0x89; 1 x 4,0x89; 1 x 5,0x89; 1 x 6,0x89