
## **Exploded Drawing of Bench Drill RDP-BD02X**





## Parts list of Bench Drill RDP-BD02X

## PART LIST

| PART<br>NO. | NAME                 | PART<br>NO. | NAME                 |
|-------------|----------------------|-------------|----------------------|
| 1           | Base                 | 39          | Shaft                |
| 2           | Fianged coloumn base | 40          | Adjusting shaft      |
| 3           | Fixing screw         | 41          | Rubber ring          |
| 4           | Coloumn              | 42          | V – Belt             |
| 5           | Bolt                 | 43          | Pulley spindle       |
| 6           | Teeth                | 44          | Pulley               |
| 7           | Table lock handle    | 45          | Bearing              |
| 8           | Table bracket        | 46          | Pulley cover         |
| 9           | Angle scale          | 47          | Washer               |
| 10          | Working table holder | 48          | Bolt                 |
| 11          | Worn pinion          | 49          | V – belt             |
| 12          | Handle               | 50          | Electric             |
| 13          | Gear                 | 51          | C – spring           |
| 14          | Pin                  | 52          | Bearing              |
| 15          | Locking handle       | 53          | Nut                  |
| 16          | Working table        | 54          | Keyway spindle       |
| 17          | Ring                 | 55          | Spindle pulley       |
| 18          | Bolt                 | 56          | Nut                  |
| 19          | Depth indicator      | 57          | Fixing screw         |
| 20          | Handle seat          | 58          | Nut                  |
| 21          | Handle               | 59          | Spring cover         |
| 22          | Handle tip           | 60          | Sping                |
| 23          | Depth scale          | 61          | Spring seat          |
| 24          | Fixing screw         | 62          | Houseing             |
| 25          | Feeding shaft        | 63          | Firing screw         |
| 26          | Fixing screw         | 64          | Switch               |
| 27          | Adjusting handle     | 65          | Wedge                |
| 28          | Fixing bolt          | 66          | C – spring           |
| 29          | Fixing screw         | 67          | Bearing              |
| 30          | Bolt                 | 68          | Rubber ring          |
| 31          | Washer               | 69          | Spindle socket       |
| 32          | Motor fixing plate   | 70          | Bearing              |
| 33          | Washer               | 71          | Spindle              |
| 34          | Nut                  | 72          | Tappeped spindle tip |
| 35          | Motor                | 73          | Chuck                |
| 36          | Motor pulley         | 74          | Adjusting block      |
| 37          | Nut                  | 75          | Bolt                 |
| 38          | Washer               | 76          | Switch seat          |