

# Cordless Drill Driver

## GSR 12V-32 | 3 601 JN7 000

---


**Table of Content**

Spare parts list..... 2

Illustration - Type..... 3

## Illustration - Type - E

3 601 JN7 000  
Issue 1  
Stand 25-05-28 **Fig./Abb. 1**



**Spare parts list**

| Item | Part Number   | Description              |
|------|---------------|--------------------------|
| 1    | 1 605 806 6TZ | Housing                  |
| 4    | 1 600 A03 6J0 | Electronics Module       |
| 5    | 1 607 200 3BP | Switch                   |
| 9    | 1 601 11C 68Z | Manufacturer's nameplate |
| 10   | 1 600 A03 6J1 | Changeover Lever         |
| 20   | 1 600 A03 6J2 | Lens                     |
| 32   | 1 600 A01 3HK | Switchover Unit          |
| 41   | 1 601 11C 69N | Sticker                  |
| 45   | 1 600 A03 6J6 | Gear Box                 |
| 70   | 2 609 110 537 | Clip                     |
| 101  | 2 609 111 496 | Screw                    |
| 107  | 1 603 435 08G | Countersunk-Head Screw   |
| 657  | 1 600 A03 6JA | Belt holder clip         |
| 802  | 1 600 A03 71F | Brushless DC motor       |
| 808  | 1 601 11A D76 | Nameplate                |