



Welding inverter **WME m 250**



STANDARD EQUIPMENT:

- welding cable
- return cable
- mask & brush

| No | Order code | Description | Quantity |
|----|----------------|----------------------------------|----------|
| 1 | 0302503503S001 | handle | 1 |
| 2 | 0302503503S002 | shell | 1 |
| 3 | 0302503503S003 | Clamping plate | 2 |
| 4 | 0302503503S004 | main control board | 1 |
| 5 | 0302503503S005 | mounting plate | 1 |
| 6 | 0302503503S006 | Power board insulation board | 1 |
| 7 | 0302503503S007 | Welding mode switch harness | 1 |
| 8 | 0302503503S008 | digital display | 1 |
| 9 | 0302503503S009 | Overheat Indicator Harness | 1 |
| 10 | 0302503503S010 | Welding Potentiometer Harness | 1 |
| 11 | 0302503503S011 | potentiometer knob | 2 |
| 12 | 0302503503S012 | Potentiometer Harness | 1 |
| 13 | 0302503503S013 | Left and right wind deflectors | 2 |
| 14 | 0302503503S014 | Positive busbar | 1 |
| 15 | 0302503503S015 | quick socket | 2 |
| 16 | 0302503503S016 | plastic panel | 1 |
| 17 | 0302503503S017 | output fixing plate | 1 |
| 18 | 0302503503S018 | machine foot | 4 |
| 19 | 0302503503S019 | bottom back plate | 1 |
| 20 | 0302503503S020 | Rectifier board insulation board | 1 |
| 21 | 0302503503S021 | Negative busbar | 1 |
| 22 | 0302503503S022 | rectifier plate | 1 |
| 23 | 0302503503S023 | Power Board | 1 |
| 24 | 0302503503S024 | Inverter board radiator assembly | 1 |
| 25 | 0302503503S025 | Fan wiring harness | 1 |
| 26 | 0302503503S026 | Universal transfer switch | 1 |
| 27 | 0302503503S027 | External force cable gland | 1 |
| 28 | 0302503503S028 | Power cord harness | 1 |
| 29 | 0302503503S029 | Filter fixing plate | 1 |
| 30 | 0302503503S030 | filter | 1 |

