

схема и части

PARTS LIST & DIAGRAM

Part	Description	Qty
1	Base	1
2	Lower Fork	2
3	Rocker Head	1
4	Bearing Pad	2
5	Bearing Pad Cap	1
6	Spindle Rod	1
7	Supporting Axle	1
8	Upper Fork	2
9	Jacking Head Seat	1

Part	Description	Qty
10	Rivet	4
11	Jacking Head Rivet	1
12	Jacking Head	1
13	Nut	1
14	Under Fork Gear	2
15	Rocker Bar	1
16	Handle	1
17	Washer	2
18	Flat Bearing Set	1

