


End Brushes P6, P10, P15, P20, P25, P35 for Drill



End brushes with shaft for drill in highly resistant crimped steel wire and very high wire density, for frontal jobs with electrical and pneumatic tools.

Applications: Frontal jobs of holes deburring, maintenance and cleaning hard to reach surfaces.

D	ART	SHAFT	B	S	Ø mm	WIRE	MAX RPM	Box	REF
4	P6	6x55	6	10	0,3	Stainless steel	20000	10	2493
15	P10	6x20	10	24	0,15	Steel	20000	12	800
15	P10	6x20	10	24	0,3	Steel	20000	12	801
15	P10	6x20	10	24	0,15	Stainless steel	20000	12	953
15	P10	6x20	10	24	0,3	Stainless steel	20000	12	954
15	P10	6x20	10	24	0,15	Brass	20000	12	804
15	P10	6x20	10	24	0,3	Brass	20000	12	805
15	P10	6x20	10	24	0,17	Liz cord	20000	12	802
18	P15	6x20	15	24	0,15	Steel	18000	12	806
18	P15	6x20	15	24	0,3	Steel	18000	12	807
18	P15	6x20	15	24	0,15	Stainless steel	18000	12	956
18	P15	6x20	15	24	0,3	Stainless steel	18000	12	957

D	ART	SHAFT	B	S	Ø mm	WIRE	MAX RPM	Box	REF
18	P15	6x20	15	24	0,15	Brass	18000	12	810
18	P15	6x20	15	24	0,3	Brass	18000	12	811
18	P15	6x20	15	24	0,17	Liz cord	18000	12	812
22	P20	6x18	20	27	0,15	Steel	18000	12	813
22	P20	6x18	20	27	0,3	Steel	18000	12	814
22	P20	6x18	20	27	0,15	Stainless steel	18000	12	961
22	P20	6x18	20	27	0,3	Stainless steel	18000	12	962
22	P20	6x18	20	27	0,15	Brass	18000	12	817
22	P20	6x18	20	27	0,3	Brass	18000	12	818
22	P20	6x18	20	27	0,17	Liz cord	18000	12	819
28	P25	6x18	25	27	0,3	Steel	18000	12	820
28	P25	6x18	25	27	0,3	Stainless steel	18000	12	2495
28	P25	6x18	25	27	0,17	Liz cord	18000	12	821
35	P30	6x18	30	30	0,3	Steel	15000	12	822
35	P30	6x18	30	30	0,17	Liz cord	15000	12	823
35	P30	6x18	30	30	0,3	Stainless steel	15000	12	981