



Welding inverter **TIG 180**



STANDARD EQUIPMENT:

- welding cable
- TIG torch
- return cable
- mask & brush

No	Order code	Description	quantity
1	0302006016S001	plastic handle	1
2	0302006016S002	outer shell	1
3	0302006016S003	IGBT inverter board	1
4	0302006016S004	Movement bracket	1
5	0302006016S005	high frequency board	1
6	0302006016S006	plastic front plate	1
7	0302006016S007	panel	1
8	0302006016S008	panel fixing plate	1
9	0302006016S009	potentiometer knob	1
10	0302006016S010	Aviation socket wiring harness	1
11	0302006016S011	Argon gas fitting	1
12	0302006016S012	quick socket	2
13	0302006016S013	output fixed panel	1
14	0302006016S014	Hall current sensor	1
15	0302006016S015	Arc pilot plate holder	1
16	0302006016S016	ground bar	1
17	0302006016S017	Chassis board	1
18	0302006016S018	rectifier plate	1
19	0302006016S019	DC fan	1
20	0302006016S020	plastic front plate	1
21	0302006016S021	back plate fixing plate	1
22	0302006016S022	rocker switch	1
23	0302006016S023	Solid external force cable fixed head	1
24	0302006016S024	Power cord harness	1
25	0302006016S025	Air valve harness	1
26	0302006016S026	Clamping plate	2

