


EXPLODED VIEW OF RDP-WCH03



	220-240V/50Hz	1700W	7500r/min
			QTY
1	screw	M6x25	1
2	Bottom plate		1
3	Threaded shaft	16*150	1
4	Gaske	φ 10- φ 18-0.5	2
5	scroll whell	31*11	1
6	Circlip 10	10	1
7	Hexagonal Screws	M8x20	1
8	Upper press plate	40*9.2	1
9	Lower pressure plate 2	40*4.8	1
10	Gasket 3.8	φ 16- φ 40-3.8	2
11	Gaske 7.6	φ 16- φ 40-7.6	2
12	Gasket 11.4	φ 16- φ 40-11.4	1
13	Lower pressure plate 1	40*8.8	1
14	protective cover assembly		
	14-1	Output shaft	20*135.2
	14-2	Bearing Cover	1
	14-3	oil seal	1
	14-4	Bearing 6202	1
	14-5	Bearing 6002	1
	14-6	protective cover	1
	14-7	Bearing 608	1
	14-8	Shaft sleeve	1
	14-9	Flat key	4x10
	14-10	Gear 1	1
	14-11	Circlip 14	14
15	Locking knob assembly 1 with screw		1
		M6*25	1
16	Sliding block		1
17	Scaleplate		1
18	Locking knob assembly 2 with screw		1
		M6*16	1
19	Baffle plate		1
20	Dust inlet		1
21	Dust outlet socket fixing seat		1
22	screw	M4*16	2
23	screw	M6x25	2
24	subhandle		1
25	subhandle cover		1
26	screw	ST4. 2x16F	2
27	gear shaft assembly		
	27-1	gear shaft	1
	27-2	big bevel gear	1
	27-3	Flat key	3x8
28	cylinder pin	4*10	2
29	gear box assembly		
	29-1	Bearing 629	1
	29-2	Bearing 608	1
	29-3	head box	1

30	Triple set screw	M5x30	4
31	Nut M6		1
32	small bevel gear		1
33	rotor assembly		
	33-1	gasket	φ 10- φ 24-1
	33-2	Bearing 6200	1
	33-3	middle cover	1
	33-4	Rotor	1
	33-5	Magnetic ring	1
	33-6	Dustproof iron sheet (608)	1
	33-7	Bearing 608	1
34	Bearing sleeve		1
35	windshield		1
36	screw	ST4. 8x70F	2
37	Stator		1
38	Tension spring		1
39	housing assembly		
	39-1	housing	1
	39-2	carbon brush holder	1
40	bevel gear	7*12*14	1
41	Speed regulator		1
			1
42	screw	ST2. 9x25F	2
43	screw	M5*35	4
44	Switch	FA5-12/2	1
45	Right handle		1
46	lampshade	ABS	1
47	screw	ST4. 2x20-F	2
48	screw	ST4. 2x16F	6
49	Left handle		1
50	Flat gasket	φ 10- φ 20-1.5	1
51	screw	M10*25	1
52	Cable Clamp plate	26T. 17x5-01	1
53	screw	ST4. 2x16F	2
54	Cable sleeve		1
55	Cable		1
56	φ150 diamond cutting sheet	φ 22.2	2
57	wrench	3.5*173	1
58	Socket wrench	13	1