


## **Spare Parts List of Cut off machine for metal RD-CM08**



## **Exploded drawing of Cut off machine for metal RD-CM08**

| partDescription of spear parts | Quan | part l | Description of spear parts | Quantity |
|--------------------------------|------|--------|----------------------------|----------|
| 1 belt cover(right)            | 1    | 33     | Dishing Screw              | 1        |
| 2 belt                         | 1    | 34     | Side Cover                 | 1        |
| 3 The big wheel of belt        | 1    | 35     | outer Hexagon Nut          | 2        |
| 4 belt cover(left)             | 1    | 36     | Small Guard                | 1        |
| 5 The cover of                 | 1    | 37     | Cross Screw                | 4        |
| 6 Bearing6202                  | 1    | 38     | Sping                      | 2        |
| 7 Armature                     | 1    | 39     | Lock pin                   | 1        |
| 8 Bearing6201                  | 1    | 40     | Small Spring               | 1        |
| 9 Stator                       | 1    | 41     | Rubber Washer              | 1        |
| 10 Anti-wind Ring              | 1    | 42     | Long Screw                 | 1        |
| 11 Housing                     | 1    | 43     | Elbow Screw                | 1        |
| 12 Carbon brush                | 2    | 44     | The Nut Holder             | 1        |
| 13 Brush holder                | 2    | 45     | Straight Pin               | 1        |
| 14 Brush cap                   | 2    | 46     | Adjustable Board           | 1        |
| 15 Cross Screw M4*40           | 4    | 47     | Fixed Board                | 1        |
| 16 left handle                 | 1    | 48     | Hexagon Nut                | 4        |
| 17 Bearing Box                 | 1    | 49     | Rubber Foot                | 3        |
| 18 Small Clamp                 | 1    | 50     | Metal Base                 | 1        |
| 19 Cross Screw M4*8            | 8    | 51     | Pin                        | 2        |
| 20 Cord Anchorage              | 1    | 52     | Chain                      | 1        |
| 21 Small Board                 | 1    | 53     | Underprop                  | 1        |
| 22 Switch                      | 1    | 54     | Cord                       | 1        |
| 23 Right Handle                | 1    | 55     | Cord Armor                 | 1        |
| 24 Outer Hexagon Nut M4        | 4    | 56     | Cross Screw                | 2        |
| 25 Big Spring                  | 1    | 57     | Anchorage of Housing Cord  | 1        |
| 26 Fixed Key                   | 1    | 58     | inner Hexagon Nut          | 4        |
| 27 Fixed Pin                   | 1    | 59     | Cross Screw                | 4        |
| 28 Spindle                     | 1    | 60     | Cross Screw                | 4        |
| 29 Fixed Protection Cover      | 1    | 61     | The small wheel of belt    | 1        |
| 30 Clamp A                     | 1    | 62     | outer Hexagon Nut          | 2        |
| 31 Cutting disc                | 1    | 63     |                            |          |
| 32 Clamp B                     | 1    | 64     |                            |          |