

# Technical Repair Data Sheet FAST-65/85

V1.1

Definition: Alignment N°: 10.01

### Material / Used spares

> Does not need spares

Tools Ref. Rubi

- > Allen key Ø 5mm
  - > Manual machine aligner / Manual machine aligner "L"

> Scoring wheel 80 Ø 10 aligner

0010/0014

0015

### References of the affected models

> 13932, 13939, 13940, 13941, 14965

RUBI





RUBI




RUBI

BUBI

BÜBI

## **Rubi Tools**






10 - Manual machine aligner

15 – Scoring wheel 80 Ø 10 aligner

14 - Manual machine aligner "L"

### Exploding



Reference 92105

version 02.02

We recommend using original spares and alignment tools of Rubi.

An actual version of this technical reparation data sheet may exist on the intranet webpage: incidence management (www.rubi.com/intranet/spv).